

# GENELEC DOUBLE BREAK DISCONNECTOR RETROFIT



**Client : Nuclear Fuel Complex**

**Location : Hyderabad**

## BEFORE RETROFIT ( GENELEC MAKE )



9 Sets (9 x 3= 27 Poles)  
of 145kV Double break  
has been replaced with  
in 18 Shutdown days



### ISSUES IDENTIFIED AT SITE

- \* Aging of Disconnector
- \* Main contacts Damage / Hot spot pits and Burns
- \* Damages of drive box and in non operating condition

### CHALLENGES

- \* Base fixing of each & every structure is not standard, without change in existing structure, terminal pad and connectors
- \* To Manufacture and deliver within stipulated time frame

### SOLUTION PROVIDED

- \* S&S Disconnectors were designed & manufactured to match existing different base mounting position & terminal connection.



FOR ENQUIRIES PLEASE CONTACT [sales@sspower.com](mailto:sales@sspower.com)