HIVELM 420kV CENTRE BREAK DISCONNECTOR RETROFIT



CLIENT: PGCIL

LOCATION: INDORE,

MADHYA PRADESH



BEFORE RETROFIT (HIVELM MAKE)





420kV 2000A (4 Poles) Live parts has been replaced

AFTER RETROFIT (S&S MAKE)





ISSUES IDENTIFIED AT SITE

- * Main contacts Hot spot pits and Burns
- * Ageing of contacts due to old supply
- * Down operating pipe and other Metallics parts rusted

CHALLENGES FACED

- * Disconnector Live parts changed matching the existing Terminal connectors
- * Down Operating pipe and Corona shield suitable for Existing arrangement

SOLUTION PROVIDED

- * Live parts changed without changing the Terminal connectors
- * Retaining the Earth Switch and Earth Fixed and suitable provision in Hamper.



FOR ENQUIRIES PLEASE CONTACT sales@sspower.com